(2)

U.S. Department of Transportation Federal Aviation Administration

FAA Form 337 (12-88)

MAJOR REPAIR AND ALTERATION (Airframe, Powerplant, Propeller, or Appliance)


Form Approved OMB No.2120-0020

For FAA Use Only

Office Identification

Administration			THE STATE OF		Charleson bearing and	lla v					No.	
instructions and	d disposition of this for each such viola	l entries. See FAR 43.9 form. This report is reation (Section 901 Fede	quired b	by	law (49 U.S.C.	142	C 43.9-1 (1). Failure	or subsequ to report c	ent rev an res	vision thereof) sult in a civil pe	for enalty not t	
1. Aircraft	Make CESSNA					Model 195						
	Serial No. 7705					Nationality and Registration Mark N195U						
2. Owner	Name (As shown PAUL W. TER	Address (As shown on registration certificate) 6000 SR 247 P.O. BOX 340 HILLSBORO, OH. 45133										
			3. For	r F	AA Use Only		111 8	2.101.70	V.	de Mes		
is approved on	inied herein complied orthiness requirement ly for the above descrit to conformity inspection for the conformity in the complication in the conformity in the confor	s and tribed action RICHARD J.	HERN	/A	NNS THINESS IN	SPE	CTOR	GL05	Shirt Shirt	NOV 2 1 20	106	
		4. Unit ide						4200	THE T	5. T	/ре	
Unit	М	Model Serial No.					Repair	Alteration				
AIRFRAME	(As described in item 1 above)									THE STANDARD TO ST	x	
POWERPLANT	e rightarisati il an Northernatura, (1	The state of the country of the state of the								. 1102 (2011) 1204 (2011) 1204 (2011)	EVO S (BS)	
PROPELLER	i i i surlique	en is store for The or store of				141	encirent			100 (100 (100 (100 (100 (100 (100 (100	14.4 14.4 15.11.4	
APPLIANCE	Type Manufacturer	A PART OF STREET	4 201 331 A 77121	The state of	does acre Use disease Problem is	906		n leaken (A) ea (A) (-10) un maari ea coult a	1096	7640 ± 1667		
			Confe	or	mity Statemen		100	de la la	11100	Legator (Asse		
A. Agency's N	lame and Address		. Com	1	B. Kind of Age	2 7 045	7 to 172		C C	Certificate No.	FE 3 1	
DANNY E. MU	The half united outland	(1 · · ·)	X	U.S. Certificated Mechanic			000000		000 114 1214	ADMY D		
1661 REDKEY WINCHESTER		Taplata Per	sal R	5	Foreign Certificate	ed Me	chanic	ru-Pitasie	10. 34.	T TON		
THE STATE OF LINE				Certificated Repai	r Stat	ation		Albi				
Castanania Securi					Manufacturer			701 [14]	MARK		gart da	
hereto hav	e been made in ac	alteration made to the cordance with the requ s true and correct to the	irement	ts	of Part 43 of the	abo	ve and de 5. Federal	scribed on Aviation Re	the rev	verse or attack ons and that t	nments ne	
Date	11/ 2001		Signa	atu	ire of Authorize	d Ind	idflual -	Taret III	DEST			
11-0	4-2006	partit at a	11.38	14	4			B-Z-M				
Durane	to the outbasits =		1.0000000000	-	or Return To S	Ché siate		Jensey Activity		ida aisma	Anal.	
the Admi	nistrator of the Fe	ven persons specified be deral Aviation Administr	ration a	nd	is APPROV	n Itel ED	m 4 was ir [REJECTE		nanner prescri	bed by	
BY FAA	Fit. Standards Manufacturer		X	1	Inspection Authorization Other		Other (S)	r (Specify)				
	AA Designee	Repair Station	61 (1)	1	Person Appoved by Transport Canada Airworthings Group			971 41-4	44.64	والمتلام		
Date of Approv	al or Rejection	ion No.	1	Signature of			djvidual					
11-214	12006	- C	100	1				1				

N195U S/N 7705 11/12/06 TACK 2413.2



tr 1

NOTICE

Weight and balance or operating limitation changes shall be entered in the appropriate aircraft record. An alteration must be compatible with all previous alterations to assure continued conformity with the applicable airworthiness requirements.

8. Description of Work Accomplished

(If more space is required, attach additional sheets. Identify with aircraft nationality and registration mark and date work completed.)

N195U S/N 7705 TACH, 2473.2

DATE 11/12/2006

1. REMOVED ORIGINAL LANDING LIGHT ASSEMBLY.

2, INSTALLED AERO VISIONS INTERNATIONAL, INC. Xe VISION 14V LANDING LIGHT KIT (HID) HIGH INTENSITY DISCHARGE AND GRIMES G-3800A RETRACTABLE LANDING LIGHT ASSEMBLY, USINGING EXISTING ELECTRICAL WIRING AND EXISTING STRUCTUAL NOT ALTERED.

3, DATA:

THE AUGUST CESSNA 195 SERVICE MANUAL HORELING

AC 43.13-1B CH. 7 (SEC. 3). CH. 10 (SEC. 2) PAR. 10 AND 20. CH 11 (SEC.3) PAR.11-31, 32, 36, 45 (SEC5) PAR. 11-48 (SEC 17) PAR. 11-231

XeVISION INSTALLATION AND OPERATION MANUAL.

GRIMES INSTALATION AND PARTS CATALOG G-3800A SERIES ELECTRICAL RETRACTABLE LANDING LIGHT ASSEMBLIES.

4. OPERATIONAL TEST CHECKED GOOD.

5, LOG BOOK ENTRY, EQUIPMENT LIST, AND WEIGHT AND BALANCE UPDATED.

6, PER AC43-210, INSTRUCTIONS FOR CONTINUED A!RWORTHINESS (ICA) CHECKLIST.

- 1, INTRODUCTION: SEE BLOCK 1 OF THIS 337. THIS INST. WAS ACCOMPLISHED IN ORDER TO GAIN BETTER LANDING AND TAXI LIGHT ILLUMINATION. LONGER LAMP LIFE (2000 TO 3000 HRS) COMPARED TO 10-25 HRS OF A TUNGSTEN FILAMENT LAMP. REDUCTION IN CURRENT DRAW FROM 22 AMPS TO 4 AMPS, AND FOUR TIMES THE BRIGHTNESS OF THE ORIGINAL LAMP. USES EXISTING WIRING EXCEPT FOR TWO FOOT CABLE FROM BALLAST TO GRIMES ASSEMBLY.
 - 2, DESCRIPTION: XeVISION HIGH INTENSITY DISCHARGE LANDING LIGHT INSTALLATION AND GRIMES ELECTRICALLY RETRACTABLE LIGHT ASSEMBLY.
 - 3, CONTROL, OPERATION INFORMATION: LIGHT AND RETRACTION IS CONTROLLED WITH ORIGINAL EXISTING WIRING AND SWITCHES. THERE ARE NO SPECIAL PROCEDURES.
 - 4, SERVICING: COMPONENTS ARE NOT FIELD REPAIRABLE AND MUST BE REPLACED WITH APPROVED COMPONENTS.
 - 5, MAINTENANCE: AT 100 HR AND ANNUALS INSP. TO BE ACCOMPLISHED I/AW AC43.13-1B CH. 17. SWITCHES ARE TO BE MAINTAINED I/AW APPLICABLE AIRCRAFT SERVICE MANUAL.
 - 6, TROUBLE SHOOTING: (A) SHOULD CIRCUIT BREAKER POP FREQUENTLY, REPLACE BALLAST UNIT (B) HID DOES NOT ILLUMINATE, ILLUMINATES SLOWLY OR IS WEAK, REMOVE BULB AND OR BALLAST, VERIFY FUNCTION, REPLACE AS REQUIRED.
- 7, REMOVAL/REPLACEMENT: REFER TO THE APPLICABLE FAA FORM 337 FOR INFORMATION CONCERNING REMOVAL AND REPLACEMENT. THE HID LIGHT IS TO REMOVED AND INSTALLED IN THE SAME MANNER AS THE ORIGINAL EQUIPMENT PER APPLICABLE ACFT SERVICE MANUAL... THE STARTER/BALLAST IS ATTACHED WITH STANDARD HARDWARE USING STANDARD TORQUE VALUES. THE WIRE HARNESS BETWEEN THE LIGHT AND STARTER/BALLAST SHALL BE REMOVED AND RECONNECTED I/AW XeVISION INSTALLATION OPERATION MANUAL.
- 8, DIAGRAM: SEE ATTACHED ELECTRICAL DIAGRAM.
- 9. SPECIAL INSPECTION: N/A
- 10, PROTECTIVE TREATMENT: N/A
- 11, DATA: AC43.13-1B PAR. 7-40 FOR TORQUE VALUES OF MOUNTING HARDWARE. CHAP.11 FOR INSP AND CARE OF ELECTRICAL SYSTEMS. ACFT SERVICE MANUAL FOR SWITCHES AND WIRING. XeVISION INSTALLATION MANUAL.

the second production of the second the same of the same and

- 12, SPECIALTOOLS: N/A
- mail and the first 13, COMMUTER CATEGORY ACFT: N/A
- 14, RECOMMENDED OVERHAULS: NO ADDITIONAL OVERHAUL TIME LIMITATIONS.

3 10 100 100

- 15, AIRWORTHINESS LIMITATIONS: NOT APPPLICABLE
- 16, REVISIONS: REVISIONS TO THE ABOVE INSTALLATION TO BE SUBMITTED TO LOCAL FSDO WITH A COPY OF THIS 337 FOR APPROVAL. to the second of the second of

X Additional Sheets Are Attatched