6
US Department
of Transportation
Federal Aviation
Administration

Form Approved OMB No. 2120-0020 11/30/2007	Electronic Tracking Number				
For FAA Use Only					

<b>W</b>		MA IO	D DEDAID AND	1 A I 7	FEDATIO	N	11/30/2007			
US Department of Transportation (Airframe, Powerplant, Propeller, or Appliance)							For FAA Use Only			
Federal Aviation Administration		tentriume, f	viivi piulit, i lu	han	, vi AP	manoc <sub>j</sub>				
INSTRUCTIONS: Print or type all entries. See Title 14 CFR §43.9, Part 43 Appendix B, and AC 43.9-1 (or subsequent revision thereof) for instructions and disposition of this form. This report is required by law (49 U.S.C. §44701). Failure to report can result in a civil penalty for each such violation. (49 U.S.C. §46301(a))										
	Nationality and Registration Mark U.S.A. N5866L					Serial No. AA-5-0066	l t			
1. Aircraft	Make American Aviation					Model AA-5		Series Traveler		
- miner of the Company	Name (As shown on registration certificate)						n on registratii			
2. 0	Rickman, Loy D.					Address RR 3 Box	Address (As shown on registration certificate) Address RR 3 Box 134			
2. Owner						05070.000	The state of the s			
			Spanner (1977)			zip 65079-930	В с	ountry USA		
				3. F	or FAA Use	e Only				
						The data identified to airworthings results described aircongreen as the congreen as the congr				
4. Тур	е			5. U	Init Identifi	cation				
Repair	Alteration	Unit	M	lake		Mod	del	Serial No.		
	V	AIRFRAME				(As described in Item 1 above)				
	D POWERPLANT									
		PROPELLER								
		APPLIANCE	Type Manufacturer							
A Agg = 1.45 A1	ama c	ddrooo	· · · · · · · · · · · · · · · · · · ·		nformity St	······································				
A. Agency's N		aaress		B.	Kind of Ager	ncy icated Mechanic	η .	1		
					rtificated Mechanic		Manufacturer rtificate No.			
				Repair Station	3.00	ranouto 110.				
- 0004 1164				Certificated	Maintenance Organization					
D.   certify that the repair and/or alteration made to the unit(s) identified in item 5 above and described on the reverse or attachments hereto have been made in accordance with the requirements of Part 43 of the U.S. Federal Aviation Regulations and that the information furnished herein is true and correct to the best of my knowledge.										
Extended rang per 14 CFR P App. B		Sign	ature/Date of Autho	rized	ndividual	^		6/07		

7. Approval for Return to Service Pursuant to the authority given persons specified below, the unit identified in item 5 was inspected in the manner prescribed by the Administrator of the Federal Aviation Administration and is

| X | Approved | Rejected | Rejected

## NOTICE

Weight and balance or operating limitation changes shall be entered in the appropriate aircraft record. An alteration must be compatible with all previous alterations to assure continued conformity with the applicable airworthiness requirements.

	· · · · · · · · · · · · · · · · · · ·	
<ol> <li>Description of Work Accomplished (If more space is required, attach additional sheets. Identify with aircraft national sheets).</li> </ol>	onality and registration mark and	l date work completed.)
	USA N5866L	03/26/07
Removed existing PAR 36 landing light from the cowl. Installed XeVisi XV-36-SL) into the vacated position. The ballast was mounted on the were reused. The provided HID wire harness from the ballast to the lig work was performed in accordance with AC43.13-1B CH. 11 (SEC 3) Finstallation instructions. Amended aircraft Weight & Balance and Equip	firewall. The existing switche ht was routed directly and se PAR 11-31, 32, 37 (SEC 4) P	(HID) light assembly (kit # es, wiring, and circuit protection ecured for chafe protection. All
The following are instructions for continued airworthiness for this altered. INTRODUCTION: This installation was accomplished to increase lar landing light, and to reduce the landing light power draw from 100 watto 2. DESCRIPTION: Removed existing landing light and installed XeVision 3. CONTROL OPERATION: The light is controlled with the existing air 4. SERVICING INFORMATION: The components are not field repairabted. SERVICING INFORMATION: The components are not field repairabted. SERVICING INFORMATION: The lighting system is to be main be performed in accordance with FAR part 43.15.  6. TROUBLESHOOTING INFORMATION: If the circuit breaker pops, in the lamp or ballast, verify function and replace as required. Bench test and operation instructions with contain warnings for bench testing.  7. REMOVAL AND REPLACEMENT INFORMATION: The HID lamp is lamp. The ballast is attached to the firewall using standard procedures the lamp shall be removed in accordance with the XeVision installation 8. DIAGRAMS: Access is through the removal of the cowl. No diagram 9. SPECIAL INSPECTION REQUIREMENTS: N/A  10. APPLICATION OF PROTECTIVE TREATMENTS: N/A  11. SPECIAL HARDWARE: N/A  12. SPECIAL TOOLS: N/A  13. COMMUTER CATEGORY AIRCRAFT: N/A  14. RECOMMENDED OVERHAUL PERIODS: N/A  15. AIRWORTHINESS LIMITATIONS: There are no additional airworth 16. REVISIONS: To revise these instructions for continued airworthines District Office with a copy of the revised FORM 337 and revised ICA.  17. IMPLEMENTATION AND RECORD KEEPING: These instructions permanent records and referred to during aircraft systems inspections	nding light illumination, to inces (stock) to 50 watts (XeVision HID light.  Craft landing light switch. The ble and must be replaced with a national in accordance with Figure 1. The ble and must be done in accordance with Figure 1. The wire has and hardware. The wire has and operation instructions. The are required.  In a letter will be submitted for continued airworthiness as a letter will be submitted.	ere are no special procedures. h approved components. AR part 43.13. Inspections are to e light does not illuminate, remove ance with the XeVision installation he same manner as the original arness between the ballast and
**************************************	**********	

Additional Sheets Are Attached