3
US Department
of Transportation
Federal Aviation
A desirable to the second

MAJOR REPAIR AND ALTERATION (Airframe, Powerplant, Propeller, or Appliance)

Form Approved OMB No. 2120-0020 11/30/2007	Electronic Tracking Number	
1	or FAA Use Only	

INSTRUCTIONS: Print or type all entries. See Title 14 CFR §43.9, Part 43 Appendix B, and AC 43.9-1 (or subsequent revision thereof) for instructions and disposition of this form. This report is required by law (49 U.S.C. §44701). Failure to report can result in a civil penalty for each such violation. (49 U.S.C. §46301(a))

Nationality and Registration Mark N8982Y

1. Aircraft Piper PA-39 Name (As shown on registration certificate) Address (As shown on registration certificate) Address 4447 E. State Highway 67 Covington, James P. 2. Owner State WI Beloit 53511 Country USA Zip 3. For FAA Use Only The data identified herein complies with the applicable airworthiness requirements and approved for the above described aircraft, subject to conformity inspection by a pe authorized in FAR 43.7. 2 2 2009 Date 5. Unit Identification 4. Type Repair Alteration Unit Make Model Serial No. (As described in Item 1 above) 1 AIRFRAME POWERPLANT PROPELLER Туре APPLIANCE Manufacturer 6. Conformity Statement A. Agency's Name and Address B. Kind of Agency U. S. Certificated Mechanic Cliff Wilewski Manufacturer Foreign Certificated Mechanic C. Certificate No. 1651 Grumman Drive Rockford Certificated Repair Station State IL City Country USA Certificated Maintenance Organization Zip 61109 I certify that the repair and/or alteration made to the unit(s) identified in item 5 above and described on the reverse or attachments hereto have been made in accordance with the requirements of Part 43 of the U.S. Federal Aviation Regulations and that the information furnished herein is true and correct to the best of my knowledge. Signature/Date of Authorized Individual Extended range fuel per 14 CFR Part 43 App. B 7. Approval for Return to Service Pursuant to the authority given persons specified below, the unit identified in item 5 was inspected in the manner prescribed by the Administrator of the Federal Aviation Administration and is Approved Rejected FAA Flt. Standards Persons Approved by Canadian Maintenance Organization Manufacturer Department of Transport Inspector BY Other (Specify) Inspection Authorization FAA Designee Repair Station Signature/Date of Authorized Individual Certificate or Designation No 6/19/2009

NOTICE

Weight and balance or operating limitation changes shall be entered in the appropriate aircraft record. An alteration must be compatible with all previous alterations to assure continued conformity with the applicable airworthiness requirements.

N8982Y

8. Description of Work Accomplished

Nationality and Registration Mark

Date

Removed existing landing lights from each wing. Installed XeVision High Intensity Discharge (HID) P/N XV3A36SL-2S-12-50-2 landing light assemblies in same positions (One in each wing located just inboard of the wing tip). The landing light ballasts were mounted to each outboard wing rib just outboard of the landing light position. The existing switches, wiring, and circuit protection were reused. The provided HID wiring from the ballasts were routed directly to the landing lights and secured for chafe protection. All work was performed in accordance with AC43.13-1B, ch 11, (sec. 3) Par. 11-31, 32,37, (sec 4) Par 11-48 and XeVision installation instructions.

The following instructions are for continued airworthiness for this alteration.

- 1. Introduction: The installation was accomplished in order to gain better randing light. Illumination and total of increase service life of the landing lights.
- 2. Description: Removed existing landing lights and installed XeVision lights bedinged evode and not bewonger
- 3. Control Operation: The lights are controlled with the existing aircraft landing light switches. There are no special procedures.
- 4. Servicing INformation: The components are not field repairable and must be replaced with approved components.
- 5. Maintenance Instructions: The lighting system is to be maintained in accordance with FAR Part 43.13. Inspections are to be performed in accordance with FAR 43.15.
- 6. Troubleshooting Information: If the circuit breaker pops, replace the ballast unit. If the light does not illuminate, remove the lamp or ballast, verify function, and replace as necessary. Bench testing must be done in accordance with XeVision installation and operation instructions which contain warnings for bench testing.
- 7. Removal and Replacement INformation: The HID lamps are removed and installed in the same manner as the original lamps. The ballst is attached with click bond fasteners, incorporating 3 studs with standard lock nuts. The wire harness between the ballast and lamps can be removed per XeVision installation instructions.
- 8. Diagrams: Access is achieved by removing the wing tip and landing light lens. No diagrams are required.
- 9. Special Instruction Requirements: N/A
- 10. Application of protective coatings: N/A
- 11. Special Hardware: N/A
- 12. Special Tools: N/A
- 13. Commuter Aircraft Category: N/A
- 14. Recommended Overhaul Periods: N/A
- 15. Airworthiness Limitations: There are none.
- 16. Revision: To revise these instructions for continued airworthiness, a letter will be submitted to the local Flight Standards District Office with a copy of the revised ICA.
- 17. Implementation and Record Keeping: These instructions for continued airworthiness are to be placed in the aircraft permanent records and referred to during aircraft systems inspections and maintenance.

----- END -----