

## MAJOR REPAIR AND ALTERATION

(Airframe, Powerplant, Propeller, or Appliance)

Form	Approved
OMB	No.2120-0020

For FAA Use Only
Office Identification

INSTRUCTIONS: Print or type all entries. See FAR 43.9, FAR 43 Appendix B, and AC 43.9-1 (or subsequent revision thereof) for instructions and disposition of this form. This report is required by law (49 U.S.C. 1421). Failure to report can result in a civil penalty not to exceed \$1.000 for each such violation (Section 901 Federal Aviation Act of 1958).

excee	d \$1,000	for each such vi	iolatio	on (Section 901	Federal A	viat	ion Act of 195	8).					_	
1. Ai	rcraft	Make Piper	Make					Model PA-44-1						
		Serial No. 4496-148					Nationality and Registration Mark N572ER							
Name (As shown on registration certificate)     BCC Equipment Leasing							Address (As shown on registration certi 3780 Kilroy Airport Way Ste 750 Long Beach, CA. 90806-2460					tificate)		
					3. I	For	FAA Use Only	у						
4. Unit Identification									5. Type					
Unit Make				Model			Serial No.			Repair	Alteration			
AIRFF	RAME	——————————————————————————————————————									Х			
POWE	ERPLANT													
PROP	ELLER													
APPLIANCE		Туре												
		Manufacturer												
		·!			6. Co	nfo	rmity Stateme	ent						
A. Ag	gency's N	ame and Addre	SS			$\perp$	B. Kind of A	gency			C. C	ertificate No.		
Embry-Riddle Aeronautical University						U.S. Certificated Mechanic				BF8F	BF8R0320			
3700 Willow Creek Road Prescott, AZ. 86301					Foreign Certificated Mechanic									
				X	Certificated Repair Station  Manufacturer									
he	ereto hav	e been made in	acco	eration made to rdance with the rue and correct	requireme	ents	entified in item of Part 43 of t	the U.S. F						
Date					Siç	gnat	ure of Authoriz	zed Indivi	dual					
				7	7. Approv	val f	or Return To	Service						
	Pursuant the Admi	to the authority	give eder	n persons speci	fied below inistration	v, th	e unit identified		4 was in	spected in		anner prescri	bed by	
BY	FAA	A Flt. Standards pector		Manufacturer			Inspection /	Authoriza		Other (S				
		A Designee	Χ	Repair Station			Person Appov Canada Airwo	rthiness Gr	oup					
Date of Approval or Rejection Certificate or Designation No.					).	Signature	of Author	rized Ind	dividual					
				BF8R0320										

## NOTICE

Weight and balance or operating limitation changes shall be entered in the appropriate aircraft record. An alteration must be compatible with all previous alterations to assure continued conformity with the applicable airworthiness requirements.

Ω	Description of Work Accomplished
	(If more space is required, attach additional sheets. Identify with aircraft nationality and registration mark and date work completed.)
	(in more space is required, attach additional sheets. Identity with anchair hattoriality and registration mark and date work completed.)
A.	Removed the existing landing lights from the nose cone.
В.	The following equipment and components were installed:
	Two XeVision XV36SL-1-14 Light Kits
	2. Two LoneStar Aviation Corp Eliminator Filters
	3. Two XV-36-SL Bulbs
C.	The installation was performed using "Installation and Operation Instructions" supplied with the XV36SL-1-14 Kit
	and LoneStar Aviation, Corp Eliminator Filter Installation Drawing # LS10003-06, Rev. 1
_	The light hollogs and noise filters are mounted an a 6"x40.5" x 062" 2024T2 aluminum plate, using appropriate
υ.	The light ballasts and noise filters are mounted on a 6"x10.5"x .063" 2024T3 aluminum plate, using appropriate
	MS hardware and spacers as needed and mounted on the left side of the nose bay floor at station 28.9 using
	Piper Factory installed nutplates.
F.	The light bulbs are installed in the original mounts in the nose cone.
	The light balbe are installed in the original meants in the noce cone.
F.	Power for the lights comes from the existing wiring for the original landing lights.
G.	The system was installed with reference to AC 43.13-1B, Chapter 11, Sections 1,3,4,5,6,8,9,10,11,15 and 17.
Н.	Instructions for Continuous Airworthiness are to inspect for chafing, condition of wiring and evidence of
	overheating of the components. This will be done in conjunction with the existing Progressive Inspection
	Program for inspection of the landing light system.
I.	Operational tests checked good.
J.	Radio interference checks were completed and no interference was found
K.	Aircraft weight and balance has been calculated and updated.
	**************************************
	Additional Chapte Are Attacked
	Additional Sheets Are Attatched