

Federal Aviation

Administration

MAJOR REPAIR AND ALTERATION (Airframe, Powerplant, Propeller, or Appliance)

Form Approved OMB No. 2120-0020

For FAA Use Only

Office Identification

INSTRUCTIONS: Print or type all entries. See FAR 43.9 FAR 43.

and dispos for each su	ition of this form. The	is report is required b 901 Federal Aviation	y law Act o	(49 U. of 1958	3 Appendix B, and S.C. 1421). Failur 8).	AC 43.9 e to repr	9-1 (or subsequent ort can result in a continuation of the contin	t revision th	ereof) for inst	ructions \$1,000,00
	Make				- Manual Control					21,000.00
	CESSN	CESSNA				Model				
1. Aircraft	Serial No.	Sorial No.				210-5				
	205-0047					Nationality and Registration Mark				
						1748Z				
2. Owner	Name (As shown on registration certification DOUGLAS R RANZ				Address (As shown on registration of 2732 LONE PINE ED WEST BLOOMFELD, MI					
		3. Fe	or EA	A. Use	ATTERATION IDE	TIPIED	HEREIN COMPLIE	S WITH THE	0.500	
			THE A	BOVE	E AIRWORTHINES E DESCRIBED AIR ON BY A PERSON A	CRAFT	SUBJECT TO CON	FORMITY	,	d
			-		MANAGEMENT MAN IV. Jan		PRISE A	HE I HOUSE IN	Ma.	
							1140	THA WIT	NHARD	
		4. Ur	nit Ide	ntifica	ation		Train	,,,,,		
Unit								5. Type		
O I III	Make			Model Seri			Serial	No.	Repair	Alteration
AIRFRAME		~~~~~~	(As d	escrib	ped in Item 1 above)				Х
POWERPLA	NT									
PROPELLER	1									
APPLIANCE	Type Manufacturer									
	Wallacturer									
A Agency's	Nome and A.L.			6. C	Conformity Statem	ent				
	Name and Address			B.	Kind of Agency			C. Certific	cate No.	
6250 N S	de Aviation Inc ERVICE DR			X	U.S. Certificated			0000		
OAKLANI	COUNTY INTE	RNATIONALA		Foreign Certificated Mechanic					-	
WATERF	ORD, MI 48327	MINITONALA			Certificated Repair Station					
-		Itoration made to the			Manufacturer					
		alteration made to the e with the requirement rect to the best of my				e and de	escribed on the rev on Regulations and	that the info	chments heret ormation	0
Date						d Instituted	vel .	0 1		
10	/16/2009				nature of Authorized	The land	w			
			7.	Appro	oval For Return To	Servic	e			
Pursuant t Administra	o the authority given pater of the Federal Avi	persons specified belo ation Administration a	ow the	e unit i	identified in item 4	was insp	ected in the manne	er prescribed	by the	
	AA Fit Standards	Manufacturer	x	Insp	pection Authorization		Other (Specify,			
	FAA Designee	Repair Station			son Approved by Tr ada Airworthiness (
1000	roval or Rejection 0/16/2009	Certificate or Designation No.			nature of Authorized	Individu	ial O	Re		

NOTICE

Weight and balance or operating limitation changes shall be entered in the appropriate aircraft record. An alteration must be compatible with all previous alterations to assure continued conformity with the applicable airworthiness requirements.

8.	Descri	ption	of	Work	Accom	plished.

(If more space is required, attach additional sheets. Identify with aircraft nationality and registration mark and date work completed.)

N1748Z 10-16-2009

REMOVED EXISTING LANDING LIGHT FROM INBOARD POSITION ON LEADING EDGE LEFT WING. INSTALLED XeVISION HIGH INTENSITY DISCHARGE [HID] LANDING LIGHT ASSEMBLY INTO THE VACATED POSITION, NO ALTERATION OF MOUNTING BRACKET

THE BALLAST WAS ATTACHED TO LANDING LIGHT INBD LEADING EDGE RIB USING CLICK BOND STUD KIT P/N 04-08020 FASTENERS, NO HOLES WERE DRILLED INTO STRUCTURE. THE EXISTING SWITCH WIRING AND CIRCUIT PROTECTION WERE RE USED ALL WORK WAS PREFORMED IN ACCORDANCE WITH AC 43.13-1B, CHAPTER 11 [SEC 3] AND XeVISION INSTALLATION INSTRUCTIONS. NET WEIGHT CHANGE IS LESS THAN 1LB, NO WEIGHT & BALANCE PREFORMED.

INSTRUCTIONS FOR CONTINUED AIRWORTHINESS

PERFORM INSPECTION ANNUALLY IN ACCORDANCE WITH FAR 43, APPENDIX D.

THE LIGHT MUST NOT BE TURNED ON ABOVE 35,000 FT MSL, DOING SO MAY CAUSE ARCING IN THE LAMP AND RUIN THE LAMP.

FOR TROUBLESHOOTING, REMOVAL AND REPLACEMENT INFORMATION REFER TO XeVISION INSTALLATION AND OPERATION INSTRUCTIONS.

*U.S.G.P.O. 1990-761-75